

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐
well well other

2. NAME OF OPERATOR

Chace Oil Company, Inc.

3. ADDRESS OF OPERATOR

313 Washington, SE, Albuquerque, NM 87108

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

Unit 'J' - 2310' FSL & 2270' FEL

AT SURFACE:

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐

(other) Spud

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☐
☐
☐

5. LEASE
Tribal Contract #71

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Jicarilla Apache

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Jicarilla Tribal Contract #71

9. WELL NO.

71-21

10. FIELD OR WILDCAT NAME

S. Lindrith, Gallup Dakota

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 10, T23N, R4W

12. COUNTY OR PARISH 13. STATE

Rio Arriba New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

7313' GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

SEP 15 1983

OIL CON. DIV.
DIST. 3

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded on 9/9/83 with Arapahoe Drilling Company @ 7:00 P. M. Ran 5 joints of 8 5/8" casing, 220' DF, actual 206'. Cemented with Woodco with 170 sks (200 CF) of Class B Neat, 3% calcium chloride, 1/4 lb/sk Flocele. Plug down @ midnight on 9/9/83. Circulated 3 barrels to surface.

Subsurface Safety Valve: Manu. and Type

Set @ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED D. W. Miller TITLE President DATE September 12, 1983

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL IF ANY:

*See Instructions on Reverse Side

AMOR

ACCEPTED FOR RECORD

SEP 22 1983

FARMINGTON RESOURCE AREA

BY 8311

CHACE OIL COMPANY, INC.

313 Washington S.E.

Albuquerque, New Mexico 87108

(505) 266-5562



WELL HISTORY

Name: Chace Oil Company, Inc.
Jicarilla Apache 71-21

Location: Unit 'J' - 2310' FSL & 2270' FEL
Section 10, T23N,R4W
Rio Arriba County, New Mexico

Elevation: 7313' GL

Projected Depth: 7600'

Estimated Formation Tops:

Ojo	2585'
Pictured Cliffs	3010'
Chacra	3360'
Cliff House	4555'
Point Lookout	5125'
Gallup	6170'
Tocito	6820'
Greenhorn	7145'
Dakota 'A'	7235'
Dakota 'D'	7375'
Burro Canyon	7480'

7/18/83:

APD submitted.

8/24/83:

APD approved.

8/29/83:

Road and pad construction commenced.

9/9/83:

Spudded on 9/9/83 with Arapahoe Drilling Company @ 7:00 P. M. Ran 5 joints of 8 5/8" casing, 220' DF, actual 206'. Cemented with Woodco with 170 sks (200 CF) of Class B Neat, 3% calcium chloride, 1/4 lb/sk Flocele. Plug down @ midnight on 9/9/83. Circulated 3 barrels to surface.