

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO.	
2. NAME OF OPERATOR SHERMAN F. WAGENS ELLER		6. IF INDIAN, ALLOTTEE OR TRIBE NAME Jicarilla	
3. ADDRESS OF OPERATOR Brana Corp., 1223 First Interstate Bldg, Albuq, NM 87102		7. UNIT AGREEMENT NAME Contract #159	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 790' fwl and 2310' fs1		8. FARM OR LEASE NAME Mobil Apache 18	
14. PERMIT NO.		9. WELL NO. 3	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 7303 Gr.		10. FIELD AND POOL, OR WILDCAT South Blanco PC	
BUREAU OF LAND MANAGEMENT FARMINGTON RESOURCE AREA		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 18-23N-2W- NMPM	
		12. COUNTY OR PARISH Rio Arriba	
		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☒
SHOOTING OR ACIDIZING ☐
(Other) ☐

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

October 19, 1983: Tested 4 1/2" casing w/1500 psi for 30", no pressure drop.
Perf Pictured Cliffs with 2 SPF from 3049 - 57 and 3061 - 66, total of
13' @ 2 SPF w/ 0.43" entry hole.
SWF with 26,200 gal of treated water and 30,000# of 20-40- sand. TP 1200psi
IR 45 BPM. Ran 101 jts of 2 3/8", 4.7#, J-55 tubing, TE 3092 set @ 3102!
Swabbed and cleaned well. Well SI on October 26, 1983 for IP test.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Morris B. Jones, Engineer DATE October 27, 1983

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side