

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. NAME OF OPERATOR  
Chace Oil Company, Inc.

3. ADDRESS OF OPERATOR  
313 Washington, SE, Albuquerque, NM 87108

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface  
**Unit 'D' - 510' FNL & 560' FWL**

14. PERMIT NO.

15. ELEVATIONS (Show whether at surface or depth)  
7322' GR

BUREAU OF LAND MANAGEMENT  
FARMINGTON RESOURCE AREA

5. LEASE DESIGNATION AND SERIAL NO.  
Jicarilla Contract #47

6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
Jicarilla Apache

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
Jicarilla Tribal Contract #47

9. WELL NO.  
17

10. FIELD AND POOL, OR WILDCAT  
South Lindrith, Gallup, Dakota

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Section 13, T23N, R4W

12. COUNTY OR PARISH  
Rio Arriba

13. STATE  
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANE <input type="checkbox"/>	(Other) <input type="checkbox"/>	
(Other) <u>spud</u> <input checked="" type="checkbox"/>		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Spudded with Arapahoe Drilling Company rig #11 at 6:00 p.m. Ran 5 joints of 8 5/8" 24# casing, 212' set at 225'. Cemented with 200 sks (236 CF) Class B neat, 1/4 lb/sk Flocele, 3% calcium chloride. Circulated 3 bbls. to surface. Plug down at 11:45 p.m.

RECEIVED  
MAY 14 1985  
OIL CON. DIV.  
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE President DATE 5/8/85

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

NMOCG



# CHACE OIL COMPANY, INC.

313 Washington S.E.  
Albuquerque, New Mexico 87108  
(505) 265-2622

RECEIVED  
MAY 09 1985  
BUREAU OF LAND MANAGEMENT  
FARMINGTON RESOURCE AREA

## WELL HISTORY

### NAME:

Chace Oil Company, Inc.  
Jicarilla Apache 47-17

### LOCATION:

Unit 'D', 510' FNL & 560' FWL  
Section 13, T23N, R4W  
Rio Arriba County, New Mexico

### ELEVATION:

7322' GR

### ESTIMATED FORMATION TOPS:

Ojo Alamo	2566'
Pictured Cliffs	2978'
Chacra	3326'
Cliff House	4500'
Point Lookout	5060'
Gallup	5762'
Juana Lopez	6778'
Greenhorn	7092'
Dakota 'A'	7174'
Dakota 'D'	7324'
Burro Canyon	7422'

### PROPOSED DEPTH:

7500'

### 8/2/84:

APD submitted.

### 8/28/84:

APD approved.

### 4/27/85:

Road and pad construction commenced.

### 5/7/85:

Spudded with Arapahoe Drilling Company rig #11 at 6:00 p.m. Ran 5 joints of 8 5/8" 24# casing, 212' set at 225'. Cemented with 200 sks (236 CF) Class B neat, 1/4 lb/sk Flocele, 3% calcium chloride. Circulated 3 bbls. to surface. Plug down at 11:45 p.m.