

SUNDRY NOTICES AND REPORTS ON WELLS

(This form is to be used to report on the progress of work on wells and to report on the results of operations on wells. It is to be filled out by the operator of the well and submitted to the nearest office of the Bureau of Land Management.)

NAME OF OPERATOR

NAME OF OPERATOR

3 Washington SE, Albuquerque, NM 87108

NAME OF WELL (Report location clearly and in accordance with any State requirements)

NAME OF WELL

Unit 'B' 2064' FNL and 358' FEL

NAME OF WELL (Report location clearly and in accordance with any State requirements)

7437' GR

Jacarcilla Apache

NAME OF WELL

NAME OF WELL

Jacarcilla Tribal Contract #47

NAME OF WELL

47-19

NAME OF WELL

South Lindrith Gallup-Dakota

NAME OF WELL

Sec. 11, T23N, R4W

NAME OF WELL

Rio Arriba

New Mexico

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO

SUBSEQUENT REPORT OF

WATER SHUT-OFF

WELL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

ACTUAL TREAT

MULTIPLE COMPLETION

FRAC TREATMENT

ALTERING CASING

ROOT OR ACIDIZING

ABANDON

SHOOTING OR ACIDIZING

ABANDONMENT

PAVE WELL

CHANGE PLAN

(Other)

status report

X

(Note: Report results of multiple completion on Well Completion or Recombination Report and Log Form.)

(When proposed or completed operations (Clearly state all pertinent details and give pertinent data, including estimated date of starting any proposed work. If well is discontinuously drilled, give substantial locations and measured and true vertical depths for all markers and great part of the work.)

Well history, days 9, 10 and 11 attached.

RECEIVED
OCT 26 1987
OIL CON. DIV.
DIST. 3

I hereby certify that the foregoing is true and correct

SIGNED

TITLE Vice President Production

DATE Oct. 7, 1987

(In space for Federal or State office use)

PROVED BY

TITLE

DATE

EDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

NMCCO

16 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Well: Jicarilla Apache 47-19313 Washington St.
Albuquerque, New Mexico 87101Page: 5Date: October 5, 1987Day #: 9 Present operation: drilling Depth today: 3689'24 hour footage: 567 Formation: sand and shaleDrill Collars: No: 2- Size: 6-7" Weight: 52,000 Bore: 2 1/2Rotary: RPM: 64 Weight on bit: 34,000 Present drilling rate: 22 ft/hourPump: Liner size: 5 1/2 Pressure: 1600 Strokes per minute: 60Mud: Vis: 37 Wt.: 9.0 W. L.: 5.0 Ph 9.5Mud additives last 24 hours: 57 gel; 6 starch; 3 caustic soda; 1 soda ash;
1 desco; 1 preservative; 8 fiber; 20 BODeviation survey: 1° @ 3086' 1° @ 3523'Bit: Run No.5: 7 7/8, V527; 859 feet, 41 1/2 hoursBreak down: 23 1/4 drilling1/4 rig service1/2 surveysDate: October 6, 1987Day #: 10 Present operation: drilling Depth today: 425224 hour footage: 563 Formation: sand and shaleDrill Collars: No: 21 Size: 6-7" Weight: 49,000 Bore: 2 1/2Rotary: RPM: 64 Weight on bit: 38,000 Present drilling rate: 22 ft/hourPump: Liner size: 5 1/2 Pressure: 1600 Strokes per minute: 60Mud: Vis: 38 Wt.: 9.1 W. L.: 6.0 Ph 9.5Mud additives last 24 hours: 50 gel; 1 starch; 1 caustic soda; 1 soda ash;
2 desco, 1 preservative; 6 fiber; 20 BODeviation survey: 1° @ 4023'Bit: Run No. 5: 7 7/8, V527, 1422 feet, 63 hoursBreak down: 22 drilling1 1/4 rig repair1/2 surveys1/4 rig service, check BOPDate: October 7, 1987Day #: 11 Present operation: drilling Depth today: 4592'24 hour footage: 340' Formation: sand and shaleDrill Collars: No: 21 Size: 6-7" Weight: 49,000 Bore: 2 1/2Rotary: RPM: 62 Weight on bit: 35,000 Present drilling rate: 16Pump: Liner size: 5 1/2 Pressure: 1600 Strokes per minute: 60Mud: Vis: 39 Wt.: 9.1 W. L.: 8.0 Ph 9.5Mud additives last 24 hours: 63 gel; 8 starch; 2 caustic soda; 3 soda ash;
2 desco; 5 fiber; 1 preservative; 20 BODeviation survey: 1 3/4° @ 4542'Bit: Run No. 5: 7 7/8; V527; 1699 ft, 78 1/2 hours Run No. 6: 7 7/8, V527, 50 ft, 3 1/2 hoursBreak down: 18 1/2 drilling1/4 rig service1 1/4 rig repair4 trip and survey