



STATE OF NEW MEXICO

ENERGY, MINERALS and NATURAL RESOURCES DIVISION
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE



BRUCE KING
GOVERNOR

August 20, 1993

ANITA LOCKWOOD
CABINET SECRETARY

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

Mr. A.S. Low
Operations Manager
Bannon Energy Incorporated
3934 FM 1960 West, Suite 240
Houston, TX 77068-3539

RE: Illegal Pits in Northwestern New Mexico

Dear Mr. Low:

Thank you for responding to my letter dated July 19, 1993 by submitting some of the C-134's requested. Attached is an updated list of pits which still require C-134 compliance, that were due in this office by August 19, 1993. Also listed are those pits that must be cleaned and netted by September 3, 1993.

You are hereby directed to submit the remaining C-134's by August 31, 1993. If you have any questions please feel free to call me at 505-334-6178.

Sincerely,

Dianna K. Fairhurst

Dianna K. Fairhurst
Deputy Oil & Gas Inspector

xc: Well File
C-134 File
Jackie Neckels - BLM Farmington

Marcus A #12

Inspected 5/11/93

- ### Marcus #4

Inspected 5/11/93

- ## Marcus #5

Inspected 5/11/93

- Marcus A #2

Inspected 5/11/93

- Marcus #2**

Inspected 5/11/93

- Grace Federal 6 #1R

Inspected 5/11/93

- Marcus #1

Inspected 5/11/93

- Marcus #3R

Inspected 5/11/93

1. Separator earthen pit, bottom covered with water, no net. Requires cleaning and netting.
2. Meter Run earthen pit dry contains debris, excess pipe, barrel, rags and bottles, no net. Requires cleaning and a C-134 exception.

Marcus A #15

D-01-23N-07W

Inspected 5/25/93

1. Production Tank earthen pit contains water covered with hydrocarbons, no net. Requires cleaning and netting.
2. Separator earthen pit contains thick hydrocarbons, no net. Requires cleaning and netting.
3. Earthen pit on pipeline row just east of the Marcus A #15 contains hydrocarbons, no net. Requires cleaning and netting.

Grace Federal 1 #1R

E-01-23N-07W

Inspected 5/25/93

1. Separator earthen pit contains water with a paraffin skim, no net. Requires cleaning and netting.

Marcus #7

N-01-23N-07W

Inspected 5/11/93

1. Production Tank earthen pit contains paraffins, no net. Requires cleaning and netting.
2. Separator earthen pit contains hydrocarbons and water, no net. Requires cleaning and netting.
3. Earthen pit just south of location contains hydrocarbons, no net. Requires cleaning and netting.

Campos #2

K-04-23N-07W

Inspected 5/25/93

1. Production Tank earthen pit contains hydrocarbons and stained soils, no net. Requires cleaning and netting.
2. Old earthen pit behind production tanks dry contains a pipe and bucket, no net. Requires cleaning and a C-134 exception.

Marcus #8

B-12-23N-07W

Inspected 5/11/93

1. Production Tank small earthen pit contains oily soils, no net. Requires cleaning and netting.
2. Separator earthen pit contains water and paraffin skim, no net. Requires cleaning and netting.

Lybrook 19 #2R

K-19-24N-06W

Inspected 5/27/93

1. Separator earthen pit contains water, no net. Requires cleaning and netting.
2. Production Tank earthen pit dry, no net. Requires cleaning and netting.

Marcus A #14

K-31-24N-06W

Inspected 5/25/93

1. Meter Run earthen pit dry, no net. Requires a C-134 exception.
2. Separator earthen pit dry, no net. Requires a C-134 exception.

Grace Federal 24 #1R

D-24-24N-07W

Inspected 6/8/93

1. Separator earthen pit contains water and paraffin skim, no net. Requires cleaning and netting.

Grace Federal 24 #2

F-24-24N-07W

Inspected 6/8/93

1. Separator earthen pit contains small amount of water, paraffin, a gallon container and weeds , no net. Requires cleaning and netting.

Lybrook Federal 24 #4

H-24-24N-07W

Inspected 6/8/93

1. Production Tank earthen pit filled with paraffin covered weeds with liquid on the bottom, no net. Requires cleaning and netting.
2. Separator earthen pit contains water, paraffin and weeds, no net. Requires cleaning and netting.

Mesa 25 #6

J-25-24N-07W

Inspected 5/27/93

1. Production Tank earthen pit contains hydrocarbons, no net. Requires cleaning and netting.

Mesa 25 #3R

M-25-24N-07W

Inspected 6/8/93

1. Separator/Production Tank combination earthen pit contains water and paraffin skim, no net. Requires cleaning and netting.