


(SUBMIT IN TRIPLICATE)

Land Office New Mexico
Lease No. NM 03397
Unit Rorox - Federal



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS


RECEIVED
JUN 22 1959

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<input checked="" type="checkbox"/>		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 19, 1959, 19

Well No. 1 is located 650' ft. from N line and 1980' ft. from E line of Section 28
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Sandoval New Mexico
(Field) (County or Subdivision) (State or Territory)



The elevation of the derrick floor above sea level is 6550' ft. (around 6549)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded: May 19, 1959
Completed - June 4, 1959
P&A 1220'
Total Depth 1165 in shale.
Slight show oil 600-87
Show water 795-805
Slight show oil 1065-1101.

PLUGGING PROGRAM:
Cemented from 1100' to 1000'
Cemented from 700 to 800'
Cemented from 500 to 600'
Cemented 10 snaks in casing to surface.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company W. F. Holmes, Operator
P.O. Box 567
Address Amarillo, Texas

By John H. Burton
John H. Burton, Asst
Title P.O. Box 1594
Santa Fe, N.M.