


(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office \_\_\_\_\_

Lease No. **NM 088979**

Unit \_\_\_\_\_



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____	
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR _____	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____	<b>X</b>
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____	
NOTICE OF INTENTION TO ABANDON WELL _____		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 2, 19 62

Well No. **1** is located **1485** ft. from **[M]** line and **165** ft. from **[E]** line of sec. **20**

**NE 1/4** (1/4 Sec. and Sec. No.) **T 18 N.** (Twp.) **R. 3 W** (Range) **N.M.P.M.** (Meridian)

**Undesig. -W** (Field) **Sandoval** (County or Subdivision) **N. M.** (State or Territory)

The elevation of the derrick floor above sea level is **6616** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spud 11-21-61, TD 1392', dry, no cores, abandoned



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Hughes & Rollins**

Address **1220 East 18th St.**

**Farmington, N. M.**

By **B. A. Hodges**

Title **Agent**