(SUBMIT IN TRIPLICATE)

Land Office	Santa	70	-60.
Lease No.			

	0		
		0	
ŀ		 	
L			- 1

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO CHANGE PLANS NOTICE OF INTENTION TO TEST WATER SHUT-OFF NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL NOTICE OF INTENTION TO SHOOT OR ACIDIZE NOTICE OF INTENTION TO PULL OR ALTER CASING NOTICE OF INTENTION TO ABANDON WELL	 SUBSEQUENT REPORT OF WATER SHUT-OFF SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING. SUBSEQUENT REPORT OF ALTERING CASING. SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR. SUBSEQUENT REPORT OF ABANDONMENT. SUPPLEMENTARY WELL HISTORY.
	 SUPPLEMENTARY WELL HISTORY RE OF REPORT, NOTICE, OR OTHER DATA)

		OTHER DATA)		
Well No. 1 Com	***************************************	January 17,		
No./4 Section 20 G. Sec. and Sec. No.)	ed 660 ft. from S lin	e and 600 ft. from W line of	sec. 20	
(Field)	(Range)	(Meridian)		
The elevation of the derrick flo	oor above sea level is	(State or Territory)		

The elevation of the derrick floor above sea level is the

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cement-ing points, and all other important proposed work)

Five sacks at surface Twenty nache at the base of the owfere pipe Forty sacks from 1250 to 1350 Fifty sucks from 39.0 to 650 Fifty szeks from 4800 to 1950 Shits five sacks from 5200 to 5295 (fotel depth)

Company Davis Oil Company Address 800 Midland bevings Building Denver, Coloredo Title Division I