Form 9-331 b (April 1962)

AUG3 1961

OIL CON. COM. GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.
	SUBSEQUENT REPORT OF ABANDONMENT. SUPPLEMENTARY WELL HISTORY.

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

		A too.	New ! caries	August 1	, 19 <u>@\$</u>	
Vell No. 23-11 is locate	ed 150ft. f	rom S line	and 250 ft. fro	om W line of se	ж	_
Major 200 . 23	and Borte	5 Feat	≅.X.P.H.	DEGI	FIVE	
(14 Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)			HUJ
Desir-Denote(Vildeet)	0.00	Levels		See perioo	g a namer w.S.	مسسا
(Field)	(Count	ty or Subdivision)		(State of Territory)	1001	

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

U. S. GEOLOGICAL SURVEY FARNINGTON, NEW MEXICO

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

TD at 6600 RB

Ben 205 Me., 54°, 1546, J-55, FRC and CFAI casings lended at 6600 RB. Camera

Hen 806 jts., 5%, 1966, J-55, SEEC and CFAI mesing landed at 6682 HB. Commuted w/125 see 90-50 Possis, by sel, and 100 see later. The well was performed at 5500-656 w/2 bullets and 2 jets/foot; framed w/123,000 gallons water and 90,000 pounds 80-40 send. The water was treated with 1% Cuile, 106 per 1000 Gallons; saling agent; 10% per 1000 gallons WiG-2 fluid loss agent; 1 gallon per 1000 gallons Hur-flo oil-water demilsifier. Breakdown 8500%, average injection rate 33 berrole per minute, maximum treating pressure 3000%, instead skutin 8700%. Percented 8950 berrole of water with no oil or game.

Barrier Land

Production Stan-50 with & juta/frost; extempted to from the formation tank
Fluid at 3400% but would not break; spotted 250 gallons 7% MCA soid; the
formation broke at 3100% but took 5 barrals per minute at 3000%. Pulled
tubing and attempted to frac; formation took 12 barrals per minute at 3000%;
pumped in 150 barrals and formation broke at 2600%. Completed the job with
36 barrals per minute injection rate, 50,000 gallons water, 27,000% 20-40
sand; instant shutin was 2500%.

Sumbbed 1500 barrels of water back; formation water was black with a chloride count of 10,000 ppm; squeezed off the perforations with 25 sax of next cement; cut pipe at 800' and left a 50-sack plug over the stub. Placed a 25-sack plug over the end of the surface pipe and a 5-sack plug at the surface w/morament.

Well plugged and abandoned at 6:30 A.M. August 1, 1961. There was no show of either gas or oil in either zone.

