

(SUBMIT IN TRIPLICATE)

Indian Agency Albuquerque

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Center 212

Allottee _____

Lease No. Albuquerque 212

1			

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF REDRILLING OR REPAIR _____
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____
NOTICE OF INTENTION TO ABANDON WELL _____	

RECEIVED
OCT 6 1958

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

U. S. GEOLOGICAL SURVEY
FARMINGTON NEW MEXICO
September 30, 1958

Well No. 1 is located 200 ft. from N line and 200 ft. from W line of sec. 20

20 20 Sec. 20 (4 Sec. and Sec. No.) 200 (Twp.) 20 (Range) 20 20 (Section)
Albuquerque P. Co. (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 7000 ft. 200

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Commenced drilling operations 9-27-58 (April 1958).
Run 200' of 3 1/2" cas. @ 126 cemented w/210 slm. Plug down 1215 ft., 9-28-58.
RIG 20 hrs. Total 3 1/2" cas. w/200' for 30 slm, hole OK.

RECEIVED
OCT 7 1958
OIL CON. COM.
DIST. 3

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company ALBUQUERQUE ENGINEERING COMPANY

Address Box 212

Albuquerque, New Mexico

By [Signature]

Title District Superintendent