

WES
THE INTERIOR
SURVEY

SUND

(Do not use for
reservoir, U.S.)

REPORTS ON WELLS

(Do not use for well or plug back to a different
well.)

1. oil well ☒
2. NAME WELDS
3. ADDRESS 187415
4. LOCATION (See space 17
below.)
AT SURFACE 1154' EEL
AT TOP
AT TOTAL
16. CHECK ALL
REPORT

REQUEST FOR
TEST WATER IN
FRACTURE OR
SHOOT OR ACID
REPAIR WELL
PULL OR ALTER CASING
MULTIPLE COMPLETE
CHANGE ZONES
ABANDON*
(other)

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☐
☒

RECEIVED

JAN 07 1987

(NOTE: Report results of multiple completion or zone
change on Form 9-320.)

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plugged and abandoned by filling hole with regular cement
from TD to surface, using 12 sacks cement. Erected hole
marker and set location. Ready for inspection.
Date completed 1-5-87.

ILLEGIBLE

JAN 09 1987

OIL CON. DIV.
DIST. 3

Approved for release
Authority: [illegible]
Series: [illegible]

Submitted

11

at

[Signature]

1-5-87

Noel Reynolds

Operator

NMOCO

APPROVED
[Signature]
FARMINGTON RESOURCE AREA