cc: 5 BLM, Albuq 1 Well File

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

BUREAU OF LAND MANAGEMENT	ACCEVED A
Sundry Notices and Reports on We	ells 30 FM (124
	Lease Number NM-0581225
1. Type of Well 6.	
0il 7 .	Unit Agreement Name
2. Name of Operator Merrion Oil & Gas Corporation	Jacob Mane
8.	
3. Address & Phone # of Operator P. O. Box 840, Farmington, NM 87499 505 327-9801	Media Entrada Unit #6 API Well No. 30-045-200 32
10.	Field and Pool
4. Location of Well, Footage, Sec, T, R, M 940' FSL & 330' FEL Sec 15, T19N, R3W, SESE	Media Entrada County and State Sandoval, NM
Notice of Intent Recompletion X Subsequent Report Plugging Back Casing Repair W Final Abandonment Altering Casing X Other Report of H ₂ S	lew Construction on-Routine Fracturing ater Shut Off onversion to Injection levels
$ m H_2S$ levels were read at the Media Entrada Unit #6 Vapors off the oil production tank had $ m H_2S$ levels of 1 water production tank had levels of 250 ppm. Gas to measure the $ m H_2S$ levels. The weather was sunny with than 5 mph.	100 ppm. Vapors off the ech tubes were used to
14. I herefor certify that the foregoing is true and	correct
Signed Title Engineer	Date July 29, 1991
George F. Sharpe	
(This space for Federal or State office use MANAGER Approved by Buan A Jana () Title RIO PUERCO RESOL	JRCE AREA Date Date