Form 9-331
(May 1963)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other Instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
NM-6997

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

1.

OIL WELL [X]	GAS WELL [ ] OTHER

7. UNIT AGREEMENT NAME

2. NAME OF OPERATOR
Eastern Petroleum Company

8. FARM OR LEASE NAME
Encino Wash

3. ADDRESS OF OPERATOR
P. O. Box 226, Farmington, New Mexico 87401

9. WELL NO.
#1

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660 FSL, 660 FEL

10. FIELD AND POOL, OR WILDCAT
Wildcat-Dalton

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec.7,T19N,R4W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
6696 GL

12. COUNTY OR PARISH	13. STATE
McKinley	New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF [ ]	PULL OR ALTER CASING [ ]
FRACTURE TREAT [ ]	MULTIPLE COMPLETE [ ]
SHOOT OR ACIDIZE [ ]	ABANDON* [X]
REPAIR WELL [ ]	CHANGE PLANS [ ]
(Other)	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF [ ]	REPAIRING WELL [ ]
FRACTURE TREATMENT [ ]	ALTERING CASING [ ]
SHOOTING OR ACIDIZING [ ]	ABANDONMENT* [ ]
(Other) _____	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Dalton tested as water tite- propose to abandone and set the following plugs:

Dalton	3269-3058	w/20sx
Top of Pipe	2470-2320	w/47sx
Surface Pipe	73-223	w/16sx
Top Plug	0-10	w/5sx

Clean up location and errect a 4'4" marker.

OIL CON. COM.
DIST. 3

RECEIVED

DEC 14 1972

U. S. GEOLOGICAL SURVEY
DURANGO, COLO.

18. I hereby certify that the foregoing is true and correct

SIGNED _Robert A. Reilly_   TITLE Vice President   DATE 12-13-72

(This space for Federal or State office use)

APPROVED BY _____   TITLE _____   DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side