

wellfile

INSPECTION TICKET

DATE 7-16-75

INSTALLATION CUBA #1 (DRY HOLE) LOCATION E-23-2IN-1W  
OPERATOR FRANKLIN, ASTON + FAIR INC. NEEDS SIGN \_\_\_\_\_

LOCATION:

CLEAN ☒ JUNKY \_\_\_\_\_ WEEDS \_\_\_\_\_

OIL & WATER SPILL \_\_\_\_\_

EDGES Clean

GENERAL APPEARANCE Good

PITS:

DIKE GOOD FILLED NEEDS WORK \_\_\_\_\_

FENCE GOOD \_\_\_\_\_ NEEDS WORK \_\_\_\_\_

CONTAINS OIL \_\_\_\_\_ AMOUNT \_\_\_\_\_

CONTAINS WATER \_\_\_\_\_ AMOUNT \_\_\_\_\_

PRODUCTION EQUIPMENT:

SEPARATOR \_\_\_\_\_ DEHY \_\_\_\_\_ COMP \_\_\_\_\_

CLEAN \_\_\_\_\_ DIRTY \_\_\_\_\_ WEEDS \_\_\_\_\_

SAFE \_\_\_\_\_ FIRE HAZARD \_\_\_\_\_

PIPED TO PIT \_\_\_\_\_

PIPED TO TANK \_\_\_\_\_

LEAKS \_\_\_\_\_

FLOWS ON GROUND \_\_\_\_\_

FLOWS BEYOND PIT \_\_\_\_\_

TANKS:

NUMBER \_\_\_\_\_ SIZES \_\_\_\_\_

CLEAN \_\_\_\_\_ DIRTY \_\_\_\_\_

OVERFLOW TO PIT \_\_\_\_\_

LOAD LINE OK \_\_\_\_\_ PUDDLES OF OIL \_\_\_\_\_

LEAKS \_\_\_\_\_ FIRE HAZARD \_\_\_\_\_

FIRE WALLS \_\_\_\_\_ GOOD \_\_\_\_\_ NEED WORK \_\_\_\_\_

INSPECTED BY [Signature]

OWNER NOTIFIED BY PHONE, MAIL, DATE \_\_\_\_\_ OFFICE \_\_\_\_\_

OTHER REMARKS:

PLA

NO DRY HOLE MARKER. DEAD MAN  
WIRES NOT CUT.