16.

UNITED AS A CONTROL OF THE INTERIOR (Other instructions on reverse side)

5. LEASE DESIGNAT

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

NM 26164

GEOLO	Œ	1	C	Α	ᄂ	5	U	۲١	/Ŀ	. Y										
 						_	-	_	_	_	_	_	_	-	-	_	_	_	-	-
								_					_							

SUNDRY NOTICES AND REPORTS ON WELLS

	Use "APPLICA	TION FOR PERMIT—" for such proposals.)					
1.	OHL GAS OTHER	Dry Hole	7. UNIT AGREEMENT NA	ME			
2.	NAME OF OPERATOR		8. FARM OR LEASE NAM	E			
	Colorado Plateau Geolo	gical Services, Inc.	BiCentennial	Freedom			
3.	ADDRESS OF OPERATOR		9. WELL NO.				
	P.O. Box 537, Farmingt	on, New Mexico 87401	Federal No. 4				
4.	LOCATION OF WELL (Report location cl See also space 17 below.) At surface	early and in accordance with any State requirements.*	10. FIELD AND POOL, OF Wildcat	R WILDCAT			
	1330' FNL - 560' FEL.	SURVEY OR AREA	Sec. 35, T13N-R6E				
14.	PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH	13. STATE			
		6255 GR	Sandoval	N.M.			

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:							
TEST WATER SHUT-OFF	_	PULL OR ALTER CASING		-	WATER SHUT-OFF REPAIRING WELL	_					
FRACTURE TREAT SHOOT OR ACIDIZE		MULTIPLE COMPLETE ABANDON*		_	FRACTURE TREATMENT ALTERING CASING SHOOTING OR ACIDIZING ABANDONMENT*	-					
REPAIR WELL (Other)	<u></u>	CHANGE PLANS		_	(Other) Commencement of operations (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)						
			77								

- 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starti proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zone nent to this work.)*
- 9/29/76 Moved in cable tool rig to drill 12%" surface hole.
- 10/7/76 Finished drilling surface hole to 87'. Ran 84', 8-5/8", 24# surface casing. Cemented w/25 sx cement, circulated to surface.
- 10/25/76 Rigged up rotary, set BOP and tested to 1000#. Held on.
- 10/27/76 Drilled out from surface casing w/62" bit.
- 10/28/76 Drilled to 620'. Damaged mast on trip. SD for rig repair
- Resumed operations. Drilled 6½" hole to 1403'. 11/15/76
- Ran Schlumberger dual induction & CNL-Density logs. 11/23/76
- 11/29/76 Spotted cement plugs 1300-1200(20 sx), 300-150(30 sx), and 10 sx in surface casing w/standard dry hole marker as approved by Mr. Jerry Long, USGS.
- 12/17/76 Filled & leveled pits. Leveled and cleaned up location. P & A complete.

8. I hereby certify that the foregoing is true and correct SIGNED Mult Eller Legislation	TITLE Vice President	DATE 9/12/77
(This space for Federal or State office use)	DEPENSED	
APPROVED BY	TITLE DEGEIVED	DATE

*See Instructions on Reverse Side VEY
U. S. GEOLOGICAL SURVEY DURANGO, COLO.