REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE

PULL OR ALTER CASING

MULTIPLE COMPLETE **CHANGE ZONES**

REPAIR WELL

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Form 9–331		Form Approved. Budget Bureau No. 42–R1424
Eec. 1973	UNITED STATES PARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	5. LEASE NM 29169 6. IF INDIAN, ALLOTTEE OR TRIBE NAME N/A
	IOTICES AND REPORTS ON WELLS of for proposals to drill or to deepen or plug back to a different 331—C for such proposals.)	7. UNIT AGREEMENT NAME N/A 8. FARM OR LEASE NAME
1. oil on 8	gas Other	Lewis 28-21-3 9. WELL NO.
2. NAME OF OP	PERATOR Prgy Corporation	#1 10. FIELD OR WILDCAT NAME
3. ADDRESS OF		Wildcat 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 28-T21N-R3W
below.) AT SURFACE: AT TOP PRO AT TOTAL DE	: 660' FNL, 660' FWL; Sec. 28,T21,R DD. INTERVAL: Same EPTH: Same	12. COUNTY OR PARISH 13. STATE Sandoval New Mexico 14. API NO.
16. CHECK APPE REPORT, OR	ROPRIATE BOX TO INDICATE NATURE OF NOTICE OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 7020 GR.
REQUEST FOR A	APPROVAL TO: SUBSEQUENT REPORT OF:	

(NOTE: Report results of multiple of

change on Form 9-330.)

SMM

BY _

OCT 16 1981

OIL' CON. COM. DIST. 3 ABANDON* (other) Commencement of Drilling. 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Well was spudded at 5:00 p.m. on October 7, 1981.

		_		Set @ Ft.
Subsurface Safety Valve: Manu. and Typ	e			
18. I hereby certify that the foregoing is	true and correct	erations	Manage b ate	October 8, 1981
	(This space for F	ederal or State	e office use)	
APPROVED BY	TITLE		DA1	E
CONDITIONS OF APPROVAL, IF ANY:				Recepted Percau
	*See Instru	tions on Reve	erse Side)CT 1 5 1981
				FARMINGTON DISCLOT