

SUNDRY NOTICES AND REPORTS ON WELLS

1. oil ☒ gas ☐ other

2. NAME OF OPERATOR
Merrion Oil & Gas Corporation

3. ADDRESS OF OPERATOR
P. O. Box 1017, Farmington, New Mexico

AT SURFACE: 1850' FSL and 1850 FWL

AT TOP PROD. INTERVAL: Same

AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,
REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) Spud ☐

Journal of Management Education 36(8) 907-921

SUBSEQUENT REPORT OF:

RECEIVED


AUG 04 1992

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

U. S. GEOLOGICAL SURVEY
ADMINISTRATIVE

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Move in, rig up Young Rig 2. Spud 8/1/82. Set 5 joints 8-5/8" @ 201' KB w/170 sx cement. (200.6 fr³)



Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Operations Manager

DATE

8/2/82

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL IF ANY:

DATE REPTED FOR RECORD

APR 5 1982

*See Instructions on Reverse Side

FAIRFAX COUNTY, VIRGINIA

64

SMM

NMOCC