FARMINGTO: BY \_\_\_\_\_\_ Sm m

5. LEASE

## UNITED STATES DEPARTMENT OF THE INTERIOR

| DEPARTMENT OF THE INTERIOR  | N00-C-14/20-5050  |
|---|---|
| GEOLOGICAL SURVEY   | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME  |
|   | Navajo Allotted 7. UNIT AGREEMENT NAME                                      |
| SUNDRY NOTICES AND REPORTS ON WELLS   | 7. UNIT AGREEMENT NAME  |
| (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)  | 8. FARM OR LEASE NAME   |
| 1. oil gas X other  | Dome Navajo 33-22-6   |
| well well other  2. NAME OF OPERATOR  | 9. WELL NO.   |
| DOME PETROLEUM CORP.  | 10. FIELD OR WILDCAT NAME   |
| 3. ADDRESS OF OPERATOR  | Rusty Chacra  |
| 3600 Southside River Rd., Farmington, NM 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17   | 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA                            |
| below.)   | Sec. 33, T22N, R6W  |
| AT SURFACE: 790' FNL, 790' FEL  | 12. COUNTY OR PARISH 13. STATE  |
| AT TOP PROD. INTERVAL: AT TOTAL DEPTH:  | Sandoval New Mexico  14. API NO.  |
| 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,   | THE ACTION.   |
| REPORT, OR OTHER DATA   | 15 ELEVATIONS (SHOW DF, KDB, AND WD)  |
| REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF   | 6923' GR  |
| REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT FEET WATER SHUT-OFF  |   |
| FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING  | 2   |
| REPAIR WELL   | (NOTE: Report results of multiple completion or zone change on Form 9–330.) |
| PULL OR ALTER CASING  | SURVEY change on Form 9-330.)   |
| MULTIPLE COMPLETE U U GEOLOGICAL CHANGE ZONES U GEOLOGICAL  | M. M.   |
| ABANDON*  |   |
| (other) Spud & Set Surface Casing   |   |
| <ol> <li>DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state<br/>including estimated date of starting any proposed work. If well is di<br/>measured and true vertical depths for all markers and zones pertinen</li> </ol> | irectionally drilled, give subsurface locations and                         |
| Spudded 12%" hole at 2:15 p.m., 11/01/82. Dril (129') 8 5/8", 24#, K55, ST&C Casing. Casing 1 with 90 sacks Class "B" Cement with 2% CaCl. PCirculated cement.  | anded at 130' G.L. Cemented   |
|   | Some Some   |
| Subsurface Safety Valve: Manu. and Type   | Set @ Ft.   |
| 18. I hereby certify that the foregoing is true and correct   |   |
| SIGNED ALL SELLINGSHAFT TITLE Area Prod. SL   | ipt. date <u>November 2, 1982</u>   |
| (This space for Federal or State off  | ice use)  |
| APPROVED BY TITLE   | DATE  |
| CONDITIONS OF APPROVAL, IF ANY:   | ASSEPTED FOR RECORD   |
| NMO( *See Instructions on Reverse S   | CC <sup>1</sup><br>NOV 4 1982   |