5 BLM, Fmn

1 McHugh

1 SoUnEx

Foim Approved.
Budget Bureau No. 42-R1424

Dec. 1973  UNITED STATES  DEPARTMENT OF THE INTERIOR  GEOLOGICAL SURVEY	<ul><li>5. LEASE</li><li>NM 28748</li><li>6. IF INDIAN, ALLOTTEE OR TRIBE NAME</li></ul>
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME  8. FARM OR LEASE NAME
1. oil well IX well other  2. NAME OF OPERATOR DUGAN PRODUCTION CORP.  3. ADDRESS OF OPERATOR P O Box 208, Farmington, NM 87499  4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 2170' FSL - 570' FEL AT TOP PROD. INTERVAL: AT TOTAL DEPTH:  16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA  REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT REFORM WATER SHUT-OFF STRACTURE TREAT SHOOT OR ACIDIZE SH	Kinsale  9. WELL NO.  2  10. FIELD OR WILDCAT NAME Lybrook Gallup Ext.  11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 26. T23N R7W  12. COUNTY OR PARISH 13. STATE Sandoval NM  14. API NO.  15. ELEVATIONS (SHOW DF, KDB, AND WD) 7214' GL; 7226' RKB
	OGICAL SURVEY  TON, N. M.  ate all pertinent details, and give pertinent dates, directionally drilled, give subsurface locations and
$5-12-83$ $5698'$ - Trip to condition hole $1\frac{1}{2}$ degree @ $5698'$ .	Wt. 9.1 Vis 65 W.L. 9.0
5-13-83 <u>TD 569<b>8'</b></u> - Laying down drill pipe.	. Wt. 9.2 Vis 62
5-18-83 Finish T.I.H. with bit. Tagged ce 5662' PBTD. Circ. hole clean.	ement at 5598'. Drilled cement to
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct  SIGNED	DATE 6-9-83
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:	office use)  ALUETTED FOR RECORD
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:	HIM 9 0 (000

NMOCO

JUN 2 0 1983