Form	9-331
Dec	1973

REPAIR WELL

ABANDON*

TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE

PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES

1 File 1 Robinson 5 BLM, Fmri

Form Approved. Budget Bureau No. 42-R1424

(NOTE: Report results of multiple completion or zone

change on Form 9-330.)

Form 9–331	0 5211,	
Dec. 1973	UNITED STATES ARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	5. LEASE NM 14970 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	OTICES AND REPORTS ON WE or proposals to drill or to deepen or plug back to a 31-C for such proposals.)	8. FARM OR LEASE NAME
1. oil ga		B.R.'s Stars 9. WELL NO.
2. NAME OF OPE DUGAN PR 3. ADDRESS OF OPE POBOX 4. LOCATION OF DELOW.) AT SURFACE: AT TOP PRODING AT TOTAL DEP	ODUCTION CORP. DPERATOR 208, Farmington, NM 87499 WELL (REPORT LOCATION CLEARLY. See s 330 FSL - 500 FEL INTERVAL: PTH:	12. COUNTY OR PARISH 13. STATE Sandoval NM 14. API NO.
16. CHECK APPRORE	TOURNE DEDOD	7125' GL; 7137' RKB

(other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Recovered 5 bbls. of mud flush, no cement. Cement top at 150'.

Cement top, 5½" casing

		A Graham
Subsurface Safety Valve: Manu. and Type		Set @ Ft.
18. I hereby certify that the foregoing is true and co	true and correct	12-27-06GEPTED FOR RECORD
SIGNED Jim L. Jaco)DS (This space for Federal or State office use)	DEC 3 0 1983
APPROVED BY	DATE	FARIMMENON RESOURCE AREA