

**ROBERT L. BAYLESS**

PETROLEUM PLAZA BUILDING  
P. O. BOX 168  
FARMINGTON, NEW MEXICO 87499  
(505) 326-2659

Natani #34  
Section 12, T21N, R6W  
1841' FNL & 1450' FEL  
Sandoval County, NM

SLOPE TEST

<u>Depth</u>	<u>Hole Deviation</u>
875'	$\frac{1}{2}^{\circ}$
1293'	$\frac{1}{2}^{\circ}$
1762'	$\frac{3}{4}^{\circ}$

State of New Mexico )  
                                  ) ss  
County of San Juan )

I, Kevin McCord, Petroleum Engineer, being first duly sworn,  
depose and state that the above and foregoing depth and hole  
deviation figures are true and correct to the best of my  
information and belief.

Kevin H. McCord

Subscribed and sworn before me this 10th day of February, 1986.

\_\_\_\_\_  
Notary Public

My Commission Expires

9-20-86

**RECEIVED**

EEB 11 1986

OIL CON. DIV.  
DIST. 3