Casing S Csg.Perf.		Sx. In	·t@_	W	Sx. Pr Prod. Stim			w	Cu.ft.		@	7 Gas
.P	BO/D _MCF/D After_	Hrs. SICI	PF	SI AfterD	Grav		1st De	el. Gas				Ä N S
Ojo Alamo	TOPS	NITD X	NITD X		Well Log		TEST DATA					
Kirtland		C-103		Plat X		Schd.	PC	1 0	T			
Fruitland		C-104		Electric Log				-	PW	PD	D	Ref.No
Pictured Ciliffs				C-122		 		ļ				<u> </u>
Chacra		Ditr		Dfa								
Cliff House		Datr		Dac								
												L
Menefee]										
Point Lookout												
Mancos												
Gallup												
Greenhorn												
Dakota		1										
ntr od a		1										
		-			ı							
		<u> </u>		Acres	161.35							
lia+vchaa	νο ς - αν •	2		H Ope r. Robert								

Natani #27

H-3-21N-6W

ROBERT L. BAYLESS

1235 La Plata Highway Farmington, New Mexico 87401

CERTIFIED—RETURN RECEIPT REQUESTED P-713-636-406

Robert L. Bayless
P.O. Box 168
Farmington, NM 87499

Gentlemen:

Enclosed are your Applications for Permit to Drill (APDs) for wells No. 27 and 29 Natani, SE/4NE/4 and NW/4SE/4 respectively, sec. 3, T. 21 N., R. 6 W., Sandoval County, New Mexico, lease NM-17007. As discussed with Kevin McCord of your Company on February 29, 1988, the subject (APDs are rescinded) and returned due to drilling not being commenced within one year of the approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred. Later discovery that construction activities have in fact occurred, may result in an assessment for noncompliance.


Sincerely,

This is a second

Ron Fellows Area Manager

2 Enclosures

cc:



ABANDONED LOCATION