


(SUBMIT IN TRIPLICATE)

Land Office New Mexico

Lease No. NM 03829 A

Unit _____



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<input checked="" type="checkbox"/>		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 1, 1959

Well No. 1 is located 367 ft. from 1/4 line and 330 ft. from E line of sec. 17

SE 1/4
(1/4 Sec. and Sec. No.)

18 North 3 West
(Twp.) (Range)

N.M.P.M.
(Meridian)

(Field)

Sandoval
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 6573 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)


Spudded: June 8, 1959
Completed-June 20, 1959
P&A
Total Depth 1510' in gray
sandy shale
No show of oil or water.

PLUGGING PROCEDURE:

Intend to: Cement from 1430 to 1485'
Cement from 700 to 850'
Cement from 500 to 625'
Cement 10 sacks in casing
to surface.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company W. W. Holmes, Operator
P.O. Box 567
Address Amarillo, Texas



By [Signature]
Title General Manager