



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office SF-01453  
Lease No. 16-08-011-2928  
Unit \_\_\_\_\_

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		<u>Subsequent report of test</u>	<u>X</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Farmington, New Mexico July 3, 1957  
Well No. 3 is located 1980 ft. from 21N line and 990 ft. from E line of sec. 23  
NE 1/4 of 21/4 Section 23 T-22-S R-7-E  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Farmington San Juan New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 4524 ft.

### DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

5/8/57: DIT 21 from 1270-1331. 1" to 1 1/2" O.D. 30 35 min. Fair blow at  
start to end of 35 min. Recovered 370' muddy water. 1 30 min.  
DIT 254, 75 454, 51. 10. 2100, 20 2400. Chloride to ditch 120 ppm, in test 1000 ppm.  
Test satisfactory.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Humble Oil & Refining Company  
Address Box 1268  
Farmington, New Mexico  
By \_\_\_\_\_  
Title J. C. Winkley  
Dist. Chief Clerk