



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Santa Fe
Lease No. SP-079279-A
Unit _____
Co. Lee. 239550

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY <u>IST</u> <u>X</u>
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

TANNER UNIT

Farmington, New Mexico September 19, 1957

Well No. 2 is located 1930 ft. from [S] line and 660 ft. from [W] line of sec. 23
SW/4 Section 23 T-23-N R-12-W
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Tanner Unit San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6033 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

9/16/57: IST #8 from 4705 - 4845 w/1" TC & 5/8" BC. TO 22 minutes. Strong blow. Water to surface in 16 minutes. Flowed at rate of 35 gals./min. Initial mud 2420#, min. fl. 1105#, max 2070#, Final 2420#, BU after 30 min. 2230#.

Received verbal approval 9/17/57.

Set cement plug as follows: No. 1 4845 - 4650 w/65 sacks neat cement. PCB 9:55 PM, 9/17/57; No. 2 4650 to 4350 w/80 . PCB at 10:35 PM; No. 3 3600 - 3400 w/70 sacks. PCB 11:50 PM; No. 4 2750 - 2650 w/40 sacks. PCB 12:35 AM, 9/18/57; No. 5 400 - 200 w/80 sacks. PCB at 2:00 AM.

Capped well. Well plugged and abandoned.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Humble Oil & Refining CompanyAddress Box 1268Farmington, New MexicoBy COPY ORIGINAL SIGNED: R. M. LILLY
Russell M. Lilly
Title Dist. Supt.

AW/

GPO 9 18 507