

X			

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. 000172-A  
Unit Rankin Federal

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	X
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 17, 1959

Well No. 2 is located 300 ft. from SW line and 300 ft. from W line of sec. 17

SW 1/4 of Sec. 17 (1/4 Sec. and Sec. No.)  
So. Blanco P. C. (Field)  
24N (Twp.)  
3W (Range)  
NMPN (Meridian)  
Rio Arriba (County or Subdivision)  
New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 5042 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On August 17, 1959. Total Depth 3146.

Ran 6 joints of 1 1/2", J-55, 15.50# casing (3132') set at 3132' with 70 sacks regular cement, 3 1/4# Floccle per sack.

Hold cement 30 minutes.

Top of cement by temperature survey at 2'30'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company E. Paso Natural Gas Company

Address Box 997

Farmington, New Mexico

ORIGINAL SIGNED H.E. McANALLY

By \_\_\_\_\_

Title Petroleum Engineer

