UNITED STATES	5. LEASE				
DEPARTMENT OF THE INTERIOR	Contract #34				
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME				
	Jicarilla Apache				
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME				
a net use this form for proposals to drill or to deepen or plug back to a different					
o not use this form for proposals to drill or to deepen or plug back to a different servoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME				
1. oil 🖼 gas 🦳	Jicarilla "C"				
well well other	9. WELL NO.				
2. NAME OF OPERATOR	16				
Getty Oil Company	10. FIELD OR WILDCAT NAME				
3. ADDRESS OF OPERATOR	Otero Gallup				
P O Box 3360, Casper, WY 82602-3360	11. SEC., T., R., M., OR BLK. AND SURVEY OR				
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA Section 34-T25N-R5W				
helow.)					
AT SURFACE: 890' FNL & 990' FWL (NW/NW)	12. COUNTY OR PARISH 13. STATE Rio Arriba New Mexico				
AT TOP PROD. INTERVAL: SAME AT TOTAL DEPTH: SAME					
71. 1017.2 32. 17.	14. API NO.				
6. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	15. ELEVATIONS (SHOW DF, KDB, AND WD)				
REPORT, OR OTHER DATA	6715' GR 6724' KB				
FOUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	6/13 GR 6/24 RB				
TOTAL WATER OF THE TOTAL	and the second s				
FRACTURE TREAT	7 \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \				
CHOOT OF ACIDIZE					
REPAIR WELL   APP 0	(NOTE: Report results of multiple completion or zone change on Form 9–330.)				
PULL OR ALTER CASING [] [ ]	Change on Your 3-3300				
MULTIPLE COMPLETE U. S. CEULUS	DUBUAL BURYEY				
CHANGE ZONES U GARLAINGTO	TON, N. M.				
(other) Request 90 days to evaluate.	Los - reappropried to the state of the state				
	to all portinent details, and give pertinent dates				
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates					

including estimated date of starting any proposed work. If well is directionally measured and true vertical depths for all markers and zones pertinent to this work.)\*

As reported on a Sundry Notice dated 2-1-82, this well is shut in with a fish consisting of a 4 3/4" bit, 5 1/2" casing scraper and 4' of 2 3/8" tubing in the well.

Getty Oil Company respectfully requests a period of 90 days to evaluate this well for possible recompletion in the Chacra and/or Pictured Cliffs formations. If recompletion is uneconomical, permission will be requested to P&A or plug back and hold.

92 day period begins May 1,1982

	,			
Subsurface	Safety Valve: Manu. and Type	Acting		Set @ Ft.
18. I her b	y certiforhat the foregoing is true and	correct Area		1 10 93 OFFIFE
SIGNED _	ANNONIER	Superintendent		4-19-02 CHEINED
	LA Skolle	space for Federal or State office use	DATE	MED 2 8 1982
APPROVED E CONDITIONS	OF APPRAMAR IFLANY: 1982	NMOCO		OIL CON. COM.
2	for JAMES F. SIMS DISTRICT ENGINEER	MINOCO		OIL DIST. 3
<b>~</b>	and the second	See Instructions on Reverse Side		