

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office San ta Fe

Lease No. 079332

Unit \_\_\_\_\_

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

\_\_\_\_\_ May 31 \_\_\_\_\_, 1956

Well No. 112 is located 1360 ft. from N line and 1367 ft. from W line of sec. 28


SW 1/4 Sec. 28 (1/4 Sec. and Sec. No.)      25 N (Twp.)      2 W (Range)      N. N. P. M. (Meridian)  
Undesignated (Field)      Rio Arriba (County or Subdivision)      New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 7210 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

~~Plan to complete well with rotary drill to a depth of 3500 feet.~~



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company E. G. DRILLING COMPANY, INC.

Address P.O. Box 1848

Farrington, New Mexico

By William C. Russell

Title Dr. of Geol.

