	9-881 a b. 1951)
Γ	-



## (SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Land Office	Santa	Fa
Lease No	्7933	2
Unit	Pederal	<b>.</b>

SUNDRY N	OTICES	AND	<b>REPORTS</b>	ON	WELLS
----------	--------	-----	----------------	----	-------

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.	SUBSEQUENT REPORT OF ALTERING CASING.
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

			<del></del>		A2(1) )	
Well N	lo. <b>25-C</b> is loc	ated	from $\begin{bmatrix} N \\ S \end{bmatrix}$ ine a	nd 🤼 ft. from	w line of se	xc. 2
ìå√	Sec. 2)	294	24	N.M.P.M.		
	(1/4 Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)		
ିର:	valin	Ric	Arriba	llev	Mexico	
	(Field)	(Co	unty or Subdivision)	(St	ate or Territory)	

The elevation of the derrick floor above sea level is 7333 ft.

## **DETAILS OF WORK**

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cement-ing points, and all other important proposed work)

Spud date March 14, 1958. On 3-15-58; Total Depth 140'.

Rem 4 joints 8 5/8", 24.5# 8.W. casing (128') set at 138' with 125 secks coment and 25 CaCl circulated to surface.

Reld 500% for 30 minutes.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may Company Den Juan Cas Corporation Address Box 997 Farmington, New Mexico Attn: E.S. Oberly Metrict Superistandent