

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency
Mearilla Tribal
Allottee **Mearilla "C"**
Lense No. **Contract #24**
Tract #79

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	Subsequent report of temporarily abandonment

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 28, 1960, 19

Mearilla "C"

Well No. **2** is located **1295** ft. from **N** line and **2295** ft. from **W** line of sec. **28**

SW/4 Sect. 28

(1/4 Sec. and Sec. No.)

25N

(Twp.)

9W

(Range)

NMZN

(Meridian)

South Blanco PG

(Field)

Rio Arriba County

(County or Subdivision)

New Mexico


(State or Territory)

The elevation of the derrick floor above sea level is ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well temporarily abandon.
Drove wooden plug in 5-1/2" OD casing at surface. Top of cement in 5-1/2" OD casing at 2400'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Shelly Oil Company**

Address **Draiser 510**

Farmington, New Mexico

(ORIGINAL SIGNED) **H. E. Aob**

By

Title **District Superintendent**