
Form 9-331 a (Feb. 1951)



## (SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Lease No. \$5 m(81334						
Barrier Committee Committe						

1,0613 1969

<b>SUNDRY</b>	<b>NOTICES</b>	AND	REPORTS	ON	WELLS OLD GLOAT SURVEY
					A ADMANAGE OF MITTER SATISFAIL

OTICE OF INTENTION TO DRILL	
OTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

Well No is locate	d ft. from ${S \brack S}$ line	and ft. from $\left\{ egin{array}{c} E \\ W \end{array} \right\}$ line of sec
95/4,586. and 86. No.)	(Twp) (Range)	(Meridian)
Sau - Wan (Field)	(County or Subdivision)	(State of Territory)

The elevation of the derrick floor above sea level is 7,235 ft.

## **DETAILS OF WORK**

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

A CRUENT PLUG WAS SET W/30 SACK CRUENT FOT 3670 - 3475
ALSO PLUGGED W/25 SK CRUENT FROM 500° TO 400°
MARKER SET AT SURFACE
LOCATION GLEANED AND PITS LEVELED



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company	CLARK & CONDEN PRODUCTION CO.	
Address	80x-842	
	Agreo, New Wextoo	By BHLeyes
	·	TitleAggut