

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY SAN JUAN GAS CORPORATION, 1716 First Natl Bldg., Tulsa, Oklahoma
(Address)

LEASE Fee WELL NO. 23-D UNIT 1 S 23 T 25 N R 2 W
DATE WORK PERFORMED 12-4-56 POOL Cavilan

This is a Report of: (Check appropriate block) ☐ Results of Test of Casing Shut-off
☒ Beginning Drilling Operations ☐ Remedial Work
☐ Plugging ☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

Drilled 91 feet of 11" hole and cemented 82' of 8-5/8" surface pipe with 50 sacks regular cement.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____
Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____
Perf Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

BEFORE

AFTER

Date of Test	_____	_____
Oil Production, bbls. per day	_____	_____
Gas Production, Mcf per day	_____	_____
Water Production, bbls. per day	_____	_____
Gas-Oil Ratio, cu. ft. per bbl.	_____	_____
Gas Well Potential, Mcf per day	_____	_____
Witnessed by _____	_____	_____

(Company)

OIL CONSERVATION COMMISSION

Name Original Signed Emery C. Arnold
Title Supervisor Dist. # 3
Date MAY 9 1957

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name Robert C. Pearson
Position Vice President
Company San Juan Gas Corporation
1716 First National Building
Tulsa, Oklahoma



OIL CONSERVATION COMMISSION		
AZTEC DISTRICT OFFICE		
No. Copies Received <u>4</u>		
DISTRIBUTION		
	NO. FURNISHED	
Operator	<u>2</u>	
Santa Fe	<u>1</u>	
Proration Office		
State Land Office		
J. S. G. S.		
Transporter		
File	<u>1</u>	<input checked="" type="checkbox"/>