


(SUBMIT IN TRIPLICATE)

Land Office Danta Fe
Lease No. SP 079601
Unit Lycia Rents



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF <u>Surface</u>	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 1, 1957

Well No. 2 is located 1650 ft. from [N] line and 990 ft. from [W] line of sec. 19

N. 4 section 19
(1/4 Sec. and Sec. No.)

35
(Twp.)

3
(Range)

N. 27. 1.
(Meridian)

D. Blanco - P.C. (Mesa)
(Field)

Rio Arriba
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

SPUNDED: 6:00 P.M., October 29, 1957.

Run & set 10-3/4" casing at 229' & cemented with 225 sacks regular cement, 2% CaCl. Cement circulated.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SHELY OIL COMPANY
Box 486
Address Deming, New Mexico

By _____
Title District Superintendent