


X



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Budget Bureau No. 42-R338.4.  
Appropriation No. 1-60.

Land Office **NM 04075**  
Lease No. **H111**  
Unit \_\_\_\_\_

SUNDRY NOTICES AND REPORTS ON WELLS

X

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 21st

59

10 890 795 22  
Well No. **NE 1/4 Sec. 22** is located **25N** ft. from **N** line and **N.M.P.M.** ft. from **E** line of sec. **22**  
**S. Blanco PC** (1/4 Sec. and Sec. No.) **Rio Arriba** (Twp.) **New Mexico** (Meridian)  
(Field) (County or Subdivision) (State or Territory)


The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

5-23-59 TD 3865' RKB. Set 118 joints 3862' of 5-1/2" OD 15.5# J-55 casing at 3865' with 100 sacks cement.

6- 4-59 Pressured up on casing to 1000#. No pressure decrease in one hour.



I understand \_\_\_\_\_ Geological Survey before operations may be commenced.

Company **158 Petroleum Center Building**

Address **Farmington, New Mexico**

By **Vice-President**

Title \_\_\_\_\_

