


THIS FORM IS NOT TO BE
USED FOR REPORTING
PACKER-LEAKAGE TESTS IN
SOUTHEAST NEW MEXICO.

NEW MEXICO OIL CONSERVATION COMMISSION NORTHWEST NEW MEXICO PACKER-LEAKAGE TEST

Operator EL PASO NATURAL GAS COMPANY				Well Name and Number Jicarilla 67 # 6			
Location of Well Unit H Sec. 19 Twp. 25 Rgc. 5			TYPE OF TEST →	Annual - (Give Year) 1973	Initial - (Give Date)	☐ NEW ☐ OWWO	
UPPER COMPLETION	Reservoir or Pool PC	☒ GAS ☐ OIL	☒ FLOWING ☐ ARTIFICIAL LIFT	Production String ☒ CASING ☒ TUBING			
LOWER COMPLETION	Reservoir or Pool CH	☒ GAS ☐ OIL	☒ FLOWING ☐ ARTIFICIAL LIFT	Production String ☐ CASING ☒ TUBING			

Date	Upper Zone		Lower Zone		
	Shut-in		Shut-in	Flow Test	
	Casing	Tubing	Tubing	Tubing	Flow Rate
6-11	268	268	230		
12	276	276	255		
13	286	286	274		
14	290	290		122	265 MCF/D
15	291	291		120	215 MCF/D

Remarks:




The results of this test indicate (No Packer Leakage) (Packer Leakage) in this well.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

APPROVED JUN 20 1973 19
NEW MEXICO OIL CONSERVATION COMMISSION
BY AK Hendrick
PETROLEUM ENGINEER DIST. NO. 3

OPERATOR EL PASO NATURAL GAS COMPANY
BY William D. Welch
TITLE Well Test Engineer
DATE June 18, 1973



E P N G
 Annual Packer Leakage Test
 1973
 JICARILLA 67 #6 (PC)
 Unit H Sec. 19-25-05
 Rio Arriba Co., New Mexico

o PC Zone o CH Zone