

		X

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 078884
Unit Canyon Largo

SUNDRY NOTICES AND REPORTS ON WELL

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

ALBERTA SLOAN - GOVERNMENT #2-13

March 8, 1956

Well No. 2-13 is located 990 ft. from XXX line and 990 ft. from E line of sec. 13

SE/4, Section 13

T-25N

R-6W

BNM

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

Wildcat

Rio Arriba

New Mexico

(Field)

(County or Subdivision)

(State or Territory)

(Canyon Largo Unit)

The elevation of the derrick floor above sea level is 6488 ft. KB

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

3-5-56 Perforated from 2518-28' & 2543-50' w/8 jets per ft

3-6-56 Sandfraced perfs w/30,000# sand w/25,200 gallons of water, flushed w/165 bbls water, Max press 2500#, Min press 1400#, FP 825#, Injection rate 42 BPM.

3-6-56 to 3-7-56 Swabbing & cleaning up after frac job

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company THE SUPERIOR OIL COMPANY

Address MIDLAND, TEXAS

By L. J. Willis (L.J. Willis)

Title Petroleum Engineer

RECEIVED

1944
JAN 10
10 10 10
10 10 10
10 10 10