



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Santa Fe**
Lease No. **078864**
Unit **Canyon Largo**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

ALBERTA SLOAN - GOVERNMENT #2-13

March 6, 19 **56**

Well No. **2-13** is located **990** ft. from **LINE** line and **990** ft. from **E** line of sec. **13**
SE 1/4, Section 13
(1/4 Sec. and Sec. No.) **T-25N** **R-6W** **BPM**
(Twp.) (Range) (Meridian)
Wildcat **Rio Arriba** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **6488** ft. **KB**

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

TOP PICTURED CLIFFS: 2517' (f3971)

TD: 2600' FBTD: 2560'

Ran 5 1/2", 14 1/2, J-55, R-2, STAC, Casing to 2600' & cemented w/125 sax. FT 1500#. Landed casing, released rotary rig 3-2-56. Moved in Spudder 3-4-56. Cleaned out cement to 2560'. Perforated 4 jets 2518-19', set 1 1/2 hours, ran bailer, no entry. Casing test OK.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **THE SUPERIOR OIL COMPANY**

Address **MIDLAND, TEXAS**

By **L. J. Willis (L.J. Willis)**

Title **Petroleum Engineer.**