

X			

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 078885
Unit Canyon Largo

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASINGS.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY..... X
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

HOME - GOVERNMENT #2-11

February 23, 19 56

Well No. 2-11 is located 990 ft. from (N) line and 1140 ft. from (W) line of sec. 11.

NW/4, Section 11

(1/4 Sec. and Sec. No.)

T-25N

(Twp.)

R-6W

(Range)

RMFM

(Meridian)

Wildcat

(Field)

Bio Arriba

(County or Subdivision)

New Mexico

(State or Territory)

(Canyon Largo Unit)

The elevation of the derrick floor above sea level is 6780 ft. KB

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

2-20-56: Perforated from 2854-60' and 2889-2901' with 8 bullets per ft.

2-21-56: Sand-fraced perfs w/30,000# sand w/30,000 gallons of water, flushed w/5000 gallons water, maximum pressures 2200#, Min press 850#, FP 800#, Injection rate 23.5 BPM.

2-21-56 to 2-22-56: Swabbing & cleaning out after frac job.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company THE SUPERIOR OIL COMPANY

Address MIDLAND, TEXAS

By L. J. Willis (L.J. Willis)

Title Petroleum Engineer