

(SUBMIT IN TRIPLICATE)

Indian Agency Marilla

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Contract No. 147

Allottee

Co. Lease No. 196123

			✖

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

JICARILLA APACHE TRIBE "J"

Torrington, New Mexico July 2, 19 57

Well No. 4 is located 990 ft. from ~~SN~~^{SN} S line and 990 ft. from ~~EW~~^E line of sec. 6

SE/A of SE/A Sect. 6

444

1994

Discussion

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

South Blanco Pictured Cliffs

210 APT-100

New Mexico

(Field)

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is 6643 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Pull 2" tubing. Run 2" tubing and set bridge plug at 2775'. Squeeze cement perforations in 3-1/2" casing from 2822' to 2878'. Pull tubing and set plug in top of casing. Cap well.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Humble Oil & Refining Company

Box 1262
Address _____

Address Farmington, New Mexico

COPY ORIGINAL
SIGNED: R. M. LILLY
By _____

By Harold W. Lilly
Title Dist. Supt.

