

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office San Antonio
Lease No. 21 - 080506
Unit Paddock

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	2
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 12, 1957

Well No. Paddock is located 1040 ft. from [N] line and 1625 ft. from [E] line of sec. 3

N 1/4 Sec. 3 (1/4 Sec. and Sec. No.) 25 N (Twp.) 3 E (Range) WPM (Meridian)
P.O. Espinosa (Field) Sanabria (County or Subdivision) New Mexico (State or Territory)

W. Wildcat
The elevation of the derrick floor above sea level is 7456 ft.


DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Production Casing: 6050.64', 2 1/2" 13.5'

A.T. Pool : Set at 4128' (p.c. 4020 - 4045')

1st. Stage Cement - 175 lbs. - 38 lbs leg : 27 lbs Pozmix
2nd. Stage Cement - 100 lbs. - 50 lbs leg : 50 lbs Pozmix.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company San Antonio Uranium Corporation

Address 211 1/2 East Main Street

Barlington, New Mexico

By Lee W. Millore

Title Agent