

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.  
NM 03010

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR  
Merrion & Bayless

3. ADDRESS OF OPERATOR  
Box 1541 Farmington, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface  
1850 FNL & 790 FWL

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
Rockhouse Canyon

9. WELL NO.  
1

10. FIELD AND POOL, OR WILDCAT  
S Blanco Pic Cliff

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
11-24N-7W

14. PERMIT NO.

15. ELEVATIONS (Show whether DP, RT, GR, etc.)  
6700 gl

12. COUNTY OR PARISH  
Rio Arriba

13. STATE  
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON\* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☒

SHOOTING OR ACIDIZING ☐

(Other) running casing

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT\* ☐

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Drilled 100' of 12 1/4" hole and sat 100' of 7-5/8" csng w/ 100sax cement  
Drilled to 2271 in 6-3/4" hole and sat 2260' of 4.5", 9.5# csngw/ 120 sax cement.  
Perforated 2173-78 and 2185-98 and water fraced w/ 30,000# 10-20 sand.  
Tested 3436 MCFG/D. Waiting on pipeline connection.

RECEIVED

OCT 4 1968

U. S. GEOLOGICAL SURVEY  
FARMINGTON, N.M.

OCT 7 1968  
OIL CON. COM.  
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED R. L. Bayless TITLE

DATE 10-2-68

(This space for Federal or State office use)

APPROVED BY TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side