UNITED STATES DEPARTMENT OF THE INTERIOR verse side)

SUBMIT IN TRIPLICATE. (Other instructions of

Form approved Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

223.00	DUDIGHTION	(-
	147	

GEOLOGICAL SURVEY							
CHIMIDDA	NOTICES	A NID	DEDORTS	\cap N	WFIIC		

	2017	ואטו	, ,	ACTIC		\sim	45	,	1/1	9	113	OI.	• •	•			
Do not	use this	form	for	proposals	to	drill	or	to	deepe	n or	plug	back	to a	a	different	reservoir	
		Use	"Al	PLICATION	ON	FOR	PF	RA	IIT'	' for	such	propo	sals.)			

Ticarilla Anache

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

	Use "APPLICATION FOR PERMIT— for such proposals.)	Jicarilla Apache
•	OIL GAS X OTHER Reentry - Multiple Zone	7. UNIT AGREEMENT NAME
_	Accused Marches Programmes	8. FARM OR LEASE NAME
: .	NAME OF OPERATOR	O. FARM OR LEASE NAME
	Continental Oil Company	AXI Apache "J"
E.	ADDRESS OF OPERATOR	9. WELL NO.
•	152 North Durbin, Casper, Wyoming 82601	17
i.	LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface	10. FIELD AND POOL, OR WILDCAT AXI Apache Area Chacra & Mesa Verde
	and we disch the Color HAII)	11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA

NE NE 820' FNL, 1100' FEL (Unit Letter

Sec. 7, T25N, R5W 12. COUNTY OR PARISH | 13. STATE 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 14. PERMIT NO. 6704' Gr., 6718' KB

Rio Arriba New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF	INTENTION TO:	SUBSEQUENT REPORT OF .			
	f				
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL		
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING		
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*		
REPAIR WELL	CHANGE PLANS	(Other)	tiple completion on Wall		
(Other)		(Note: Report results of multicompletion or Recompletion Re	eport and Log form.)		

Approval was received to reenter this well on August 20, 1971. Operations began 8-24-71 and reached a total depth of 5535'. 8 5/8" OD casing had been previously set at 428'. Lost 3075' of 2 7/8" drill pipe and 340' of 5 1/2" drill collars during drilling operations. Top of fish is at 3245' and we were unable to recover it after several days.

Verbal permission was received to plug and abandon this well on September 1, 1971 from Mr. Jerry Long (USGS) and Mr. Emery Arnold (NMOGCC). Formal approval is requested to plug and abandon the well as follows:

400 sks. - 3200-2000' - Picture Cliff & Farmington

100 sks. - 547-200' - In and out of 8 5/8" OD surface pi

10 sks. - At surface w/regulation dry hole marker

USGS (6) File(2)

U. S. GEOLOGICAL SURVEY

TITLE Administrative Supervisor DATE Sept. 2, 1971 (This space for Federal or State office use) DATE TITLE

APPROVED BY CONDITIONS OF APPROVAL IF ANY:

the foregoing is true and correct

*See Instructions on Reverse Side

^{17.} DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *