5. LEASE

## UNITED STATES DEPARTMENT OF THE INTERIOR

DEPARTMENT OF THE INTERIOR	Contract 145
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas 🔯	
well LJ well LAI other	9. WELL NO.
2. NAME OF OPERATOR	14
Southern Union Exploration	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	S. Blanco P.C., Otero Chacra, Basin Dk. 11. SEC., T., R., M., OR BLK. AND SURVEY OR
P.O. Box 2179 Farmington, NM 87495  4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA
below.)	Sec. 11-T25N-R5W
AT SURFACE: 975' FSL & 1640' FEL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: Same	Rio Arriba NM
AT TOTAL DEPTH: Same	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6787' G.L.
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	
FRACTURE TREAT SHOOT OR ACIDIZE	CFIVE
REPAIR WELL	(NOTE: Report results of multiple completion or zone
	change on Form 9-330.)
MULTIPLE COMPLETE	- 40 DOZ
	N. Corres
ABANDON* LJ LJ U. S. gro	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stating concluding estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertine.  The most recent pressure test indicated tub over the well & check the packer & tubing i necessary action to repair the well.	ing leaks. SX proposes to work
Repairs to proceed 10/15/82.	
Subsurface Safety Valve: Manu, and Type	Set @ Ft
18. i hereby certify that the foregoing is true and correct	
Dela Supery	disor pars 10/13/82
(This space for Federal or State o	
APPROVED BY APPROVAL, IF ANY:	DATE
DCIA 9 1982	
FOLLAMES F. SIMS  DISTRICT ENGINEER *See Instructions on Reverse	s Side