(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

			X
NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 26, 19 56

Well No. ___ 5 ___ is located 1650 ft. from [S] line and 990 ft. from [E] line of sec. ___ 19 ___

SE Section 19	24N	2W	NMPM
(¼ Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)
Wildcat		Rio Arriba	New Mexico
(Field)		(County or Subdivision)	(State or Territory)

The elevation of the derrick floor above sea level is 7055 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

```
5-20-56.  Total Depth 3111'.
Ran 97 joints 5 1/2", 15.50#, J-55 casing (3101') set at 3111' with 75
sacks regular cement, 75 sacks Pozmix, 4% Gel.
Held 1000# for 30 minutes.
Top of cement by temperature survey at 2100'.
```

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company ___ El Paso Natural Gas Company

Address ___ Box 997

___ Farmington, New Mexico

By ___ *J W Boyd*

Title ___ Petroleum Engineer