## G

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

,	- LIND MINAGEMENT	
Sundry Noti	ces and Reports on Wells	
L. <b>Type of Well</b> GAS		5. Lease Number SF-078835 6. If Indian, All. Tribe Name
2. Name of Operator	** · · · · ·	7. Unit Agreement N
BURLINGTON RESOURCES ON .	_	
PO Box 4289, Farmington, NM  Location of Well, Footage, Sec. 1550' FNL, 800' FEL, Sec. 1,	87499 (505) 326-9700406	Canyon large II #
12. CHECK APPROPRIATE BOX TO IND	ICATE NATURE OF NOTICE, R	REPORT, OTHER DATA
6-29-98 TIH. Circ w 6-30-98 TIH w/224 jt	Recompletion Plugging Back Casing Repair Altering Casing X Other - Tubing repair  eted Operations  NU BOP. SDON.	Change of Plans New Construction Non-Routine Fracturing Water Shut off Conversion to Injection r  s 1 %" tbg. SD over weekend. '. TOOH. SDON.
igned Manueld This space for Federal or State	Title <u>Regulatory Admir</u>	
PPROVED BY		