UNITED STATES SUBMIT IN TRIPLICATE (af y 1963)  DEPARTMENT OF THE INTERIOR verse side)  GEOLOGICAL SURVEY						n re				
C	SUNDI Do not use this for U	RY NC m for pro se "APPL	OTICES AND REPO	RTS ON or plug back to such proposal	WELLS a different reservoir.		8. IF INDIAN, ALLOTTEE	OR TRI	IRE SASCE	
OIL WELL WELL WOTHER  2. NAME OF OPERATOR  El Paso Hatural Gas Company  3. Address of OPERATOR  Box 990, Parmington, New Mexico 87401  4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*  See also space 17 below.)  At surface							7. UNIT AGREEMENT NAME  Canyon Largo Unit  8. FARM OR LEASE NAME			
							Canyon Largo Unit 9. WELL NO.  252 10. FIRLD AND POOL, OR WILDCAT  Basin Dakota 11. Sec., T., R., M., OR BLK, AND			
14. PERMIT NO.				15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6720 GL						
							<u>Rio Arriba</u>	N€	ew Mexic	
16.	Check Appropriate Box To Indicate Nature of Notice, Report, or O									
	NOTICE OF INTENTION TO:				S	UBSEQUE	EQUENT REPORT OF:			
•	T WATER SHUT-OFF		PULE OR ALTER CASING	_	WATER SHUT-OFF	x	REPAIRING V			
	CTURE TREAT		MULTIPLE COMPLETE ABANDON®	-	FRACTURE TREATMENT SHOOTING OR ACIDIZIN		ABANDONME			
	AIR WELL		CHANGE PLANS		(Other)		results of multiple completion on Wel			
-14-74 -15 <b>-7</b> 4	Ran 7 joir	its 9	rilled surface hol 5/8", 32.3#, H-40 cement. Circulat	surface						
			FEE COM COM CIST 2			1 <b>374</b>				
18. I he			ng is true and correct	Drill	ing Clerk			21 <b>-</b> 7½	· · · · · · · · · · · · · · · · · · ·	

TITLE \_

APPROVED BY \_\_\_\_\_\_CONDITIONS OF APPROVAL, IF ANY:

DATE \_\_