UNITED STATES

UNITED STATES	5. LEASE (1992) & 888	
DEPARTMENT OF THE INTERIOR	5. LEASE C. 100 100 100 100 100 100 100 100 100 10	
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
	Jicarilla Contract #12	
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME & BOOK AND STATE OF THE STATE OF T	
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)		
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME \$ \$4.25 Jicarilla Otero \$ \$2.25	
1. oil gas X other	Jicarilla Otero	
	9. WELL NO. 3. 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
2. NAME OF OPERATOR	10. FIELD OR WILDCAT NAMES 225	
Mobil Oil Corporation 3. ADDRESS OF OPERATOR	Basin Dakota = 1	
9 Greenway Plaza, Suite 2700, Houston, TX 77046		
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA 글을 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등	
below.)		
AT SURFACE: 840' FNL & 1800' FWL, Sec. 28,	12. COUNTY OR PARISH 13. STATE 2	
AT TOP PROD. INTERVAL: T24N, R5W AT TOTAL DEPTH:	Rio Arriba, 5 New Mexico	
	14. API NO. The state of the st	
 CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 		
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6648GR 소통하다 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등	
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:		
TEST WATER SHUT-OFF	d report pool to tother to tother of tother of tother of	
FRACTURE TREAT	jar bi e yan boot biu fian fian fian aems	
SHOOT OR ACIDIZE	(NOTE: Report results of multiple completion or zone	
PULL OR ALTER CASING [change om:Form 9-330.) ප ් දී ල ද	
MULTIPLE COMPLETE	elloisarder sitarso lles orgasis to l orgasis to l organis ett b roll organis to organis ett bron organis ett bron o	,
CHANGE ZONES		
(other)	and the state of t	,
6/23 - 28/78: Pf. 5½" csg. 5548-78, 5590-5616, 5 w/ 7500 gal. 15% HCl + 100 RCNBS. 6/29/78: Isolated perfs. 5684-5752, treated w/3 Frac'd down csg. in 3 stages w/60,000 gal. gelle TCP 1100-1790# @ 44 BPM, ISIP 1000#, 10 min 850 6/30/78: 13 hr. SICP 475#, flowed 840 BLW in 6 72 BLW/3 hrs. No shows1 7/4 & 5/78: Ran 2 3/8" tbg to 5795, pfs. @ 5758, 230 - 3/4" rods. Released rig 1 pm, 7/5. Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the seregoing is true and correct	397 w/200 sx B + 1% Halad 9 + 2% CaCl . 5620-28, 5634-46 55684 57.52 and Acidized 1576 140 graph of the color	
(This space for Federal or State off		
	DATE	***********
APPROVED BY TITLE TOTAL	జెజ్డ్లు ఉన్నాయి. మీర్	
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:		
Orig. & 2: USGS, Durango	The state of the s	
Orig. & 2: USGS, Durango 3: NMOCC, Aztec	To charge 10 Continues and the	
Orig. & 2: USGS, Durango	Side Side E 1978	
Orig. & 2: USGS, Durango 3: NMOCC, Aztec		
Orig. & 2: USGS, Durango 3: NMOCC, Aztec	side U. S. GEOLDGICAL SURVEY	