UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

9–331 1973	Form Approved. Budget Bureau No. 42–R1424
UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	Santa Fe 078913
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME
	Lindrith B Unit 8. FARM OR LEASE NAME
1. oil gas other	9. WELL NO.
2. NAME OF OPERATOR	11
Mobil Producing TX. & N.M. Inc.	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Chacon-Dakota Associated
9 Greenway Plaza, Suite 2700, Houston, TX 77046	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA
below.)	Sec. 16, T24N, R3W
AT SURFACE: 860 FSL & 885 FWL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: Same as surface	Rio Arriba New Mexico
AT TOTAL DEPTH: Same as surface	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
PURCEASE FOR APPROVAL TO CURRENT REPORT OF	7107- GR
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	· . *
TEST WATER SHUT-OFF	
FRACTURE TREAT	The Control of the Co
REPAIR WELL DE DEC	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	change on Form 9-330.)
MULTIPLE COMPLETE	
CHANGE ZONES	·
ABANDON*	
(cther) Run 45" csg.	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertine	directionally drilled, give subsurface locations and
11-29-80 - TD of 7796 @ 2 AM.	
11-30-80 - Ran Ind CNL Density Log	
12-01-80 - Ran 217 jts 4½" csg: 71 jts (2298")) 11.6# ST&C K-55,111 jts (4336')
10.5# K-55 ST&C, 35 jts (1146') 11.0	6#. Set @ 7779. BJ cmt in 2
stages w/DV @ 6001.	
(a) 7779 BJ cmt in 2 stages w/DV @	6001
1) 175x Lt + 250x B Neat - cm	
2) 450x Lt + 50x B Neat. PD @	
•	1 DEC

3. ADDRESS OF OPERATOR	Chacon-Dakota Associated	
3 Greenway Plaza, Suite 2700, Houston, TX 77046	11. SEC., T., R., M., OR BLK. AND SURVEY OR	
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA	
below.)	Sec. 16, T24N, R3W	
AT SURFACE: 860 FSL & 885 FWL	12. COUNTY OR PARISH 13. STATE	
AT TOP PROD. INTERVAL: Same as surface	Rio Arriba New Mexico	
AT TOTAL DEPTH: Same as surface	14. API NO.	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,		
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)	
	7107- GR	
RI:QUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	· . *	
TEST WATER SHUT-OFF		
FRACTURE TREAT		
SHOOT OR ACIDIZE REPAIR WELL DECLIFIED DECLIFIED SHOOT OR ACIDIZE DECLIFIED DECLIF	(NOTE: Report results of multiple completion or zone	
PULL OR ALTER CASING	change on Form 9-330.)	
MULTIPLE COMPLETE	- · · · · - · · · · · · · · · · · · · ·	
CHANGE ZONES	•	
ABANDON*		
(cther) Run 4½" Csg.		
11-29-80 - TD of 7796 @ 2 AM. 11-30-80 - Ran Ind CNL Density Log 12-01-80 - Ran 217 jts 4½" csg: 71 jts (2298') 11.6# ST&C K-55,111 jts (4336') 10.5# K-55 ST&C, 35 jts (1146') 11.6#. Set @ 7779. BJ cmt in 2 stages w/DV @ 600!. (a) 7779 BJ cmt in 2 stages w/DV @ 6001 1) 175x Lt + 250x B Neat - cmt circ 2) 450x Lt + 50x B Neat. PD @ 1 AM 12-2-80.		
Subsurface Safety Valve: Manu. and Type Set @ Ft. f.		
18. I hereby certify that the foregoing is true and correct		
SIGNED TITLE Authorized Agent DATE 12-3-80		
(This space for Federal or State office use)		
APPROVED BY TITLE DATE CONDITIONS OF APPROVAL, IF ANY:		

