DEPARTMENT OF THE INTERIOR	5. LEASE Santa Fe 078913
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME Lindrith B Unit
1 oil — gre —	8. FARM OR LEASE NAME
well to well other	9. WELL NO.
2. NAME OF OPERATOR Mobil Producing TX. & N.M. Inc.	14 10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Chacon-Dakota Associated
9 Greenway Plaza, Ste 2700, Houston, TX 77046	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	AREA Sec. 16, T24N, R3W
AT SURFACE: 1810 FNL & 1084 FWL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: Same as surface AT TOTAL DEPTH: Same as surface	Rio Arriba New Mexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.	14. API NO.
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDE AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT OFF	
FRACTURE TREAT	
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING U U \ \ \\\\\\\\\\\\\\\\\\\\\\\\\\\\\	change on Form 9–330.)
CHANGE ZONES	
ABANDON*  (other) Spud. set 13-3/8" csg.	
(one-) Shade SEC IN-110 CSE.	``_

- - 2-5-81 Spud 17½" hole @ 12:30 PM. Ran 7 jts. 13-3/8" 48# H40 ST&C CSG. Set @ 300 w/300x B + 2% CaCl2 + 1/4# FC. PD @ 1 AM 2-6-81. Cont. drlg. 11" hole.

Subsurface Safety Valve: Manu. and Type	<b>Set</b> @ Ft
18. I hereby certify that the foregoing is true and correct	
SIGNED TITLE AL	thorized Agent DATE 2-9-81
	Federal or State office use)
APPROVED BY TITLE	DATE
FERTA 1981	
WILDIAN OTON AND ANT	A.

\*See Instructions on Reverse Side