## UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

orm 9–331	Form Approved. Budget Bureau No. 42-R1424
UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR  GEOLOGICAL SURVEY	NM 0556030  6. IF INDIAN, ALLOTTEE OR TRIBE NAME
GEOLOGICAL SURVEY	
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
Do not use this form for proposals to drill or to deepen or plug back to a different servoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME R D & P
1. oil gas uell other	9. WELL NO. 2
2. NAME OF OPERATOR	10. FIELD OR WILDCAT NAME
Roze Oil Co.  3. ADDRESS OF OPERATOR	Puerto Chiquito Fast Mancos
P.O. Box 2678 Farmington, N.M.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	Sec. 3 T25W-R1E
below.) AT SURFACE: 1980/S 1930/W	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	Rio Arriba N.M.
AT TOTAL DEPTH:  16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO.
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	TIVE Days and the second
	EIVED
REPAIR WELL OCT	5 (NOTE: Report results of multiple completion or zone change on Form 9–330.)
	ND MANAGEMENT PESOURCE AREA
ABANDON*   (other) Waiting on Frac information	•
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly st including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertin We are still waiting on Frac recommendation.	ent to this work.)*
4 days, to keep water off the formation. The every 3-4 days.	
	NOV.2 6 1984 OIL CONDIST. 3
	<u>.</u>
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct	
SIGNED 7777Brown TITLE	DATE
. (This space for Federal or State	office use)
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:	ACCEPTED FOR RECORD
	OCT 22 1984

\*See Instructions on Reverse Side

TARMINGTUN NESCONCE AKEA SMM RY